

## ABSTRACT OF THE DISCLOSURE

A method of forming a bump includes performing wet etching a bonding pad on the wafer, and then sequentially forming an under ball metallurgy layer and a bump. Hillocks on the bonding pad can be removed after the wet etching process, and the bump has a

5 planar or concave surface, whereby no nodules are formed on the bump.

10034976-122704